
# PROPERTY REPORT

October 2018



# 2018 MAIN STREET

Niagara Falls, New York



Matthew Chavez

Niagara-Orleans Regional Land Improvement Corp. (NORLIC) 716-278-8751 • Matthew.Chavez@niagaracounty.com niagaraorleanslandbank.com



Jon Claeys AIA

CJS Architects
716-856-6448 • JClaeys@cjsarchitects.com
cjsarchitects.com



Derek King
Preservation Studios
716-725-6410 • info@preservationstudios.com
preservationstudios.com

The information provided in this report was compiled by CJS Architects in October 2018. Any developer should contact CJS Architects for any questions or concerns regarding its content.

November 6th, 2018

Mr. Robert Richardson
Managing Partner
Niagara Falls Development Fund One
500 Seneca St
Buffalo, New York 14204



Re: Niagara Falls Property/ Building Assessments

Mr. Richardson,

On October 17<sup>th</sup> & 19<sup>th</sup>, 2018 CJS Architects, along with representatives from Siracuse Engineers PC, M/E Engineering, and Sienna Environmental Technologies set out to field survey 38 various properties/ buildings in Niagara Falls, NY, with the purpose of providing cursory general conditions reports for each property/ building surveyed. A typical survey lasted less than one hour, and the intent of the reports is to share first impressions of overall conditions only. A more detailed survey of each property will be required to evaluate, verify, and expand upon the initial commentary presented herein. The following is a list of the properties that were to be visited:

1628 Main St	830 Lincoln Pl
1632 Main St	813 Cleveland Ave
1636 Main St	819 Cleveland Ave
1708 Main St	2001 Main St
1802 Main St	2011 Main St
1810 Main St	2019 Main St
1812 Main St	2025 Main St
811 Division Ave	2109 Main St
717 Division Ave	2111 Main St
723 Division Ave	2113 Main St
803 Division Ave	2217 Main St
1643 ½ 8 <sup>th</sup> St	2637 Main St
1902 Main St	917 Niagara Ave
1908 Main St	915 Niagara Ave
2002 Main St	1509 Main St
2018 Main St	1105 Cleveland Ave
802 Lincoln Pl	1600 Cleveland Ave
808 Lincoln Pl	1010 South Ave
826 Lincoln Pl	1915 10 <sup>th</sup> St

Attached for your use/ review are individual surveys of each of the properties/ buildings listed above. Please contact our office should you have questions related to any of the information within.

For the purposes of grading various building components/systems, the Structural and Architectural reports utilized the following 1-5 ranking system to evaluate building components/systems:

- 1. Building component/ system completely failing, recommend complete removal, replacement, and/or demolition.
- 2. Building component/ system in extreme disrepair, reuse would require extensive cost/labor but could be accomplished.
- 3. Building component/system in in a state of general disrepair, reuse feasible depending on costs.
- 4. Building component/ system in generally good condition, reuse would require little repair.
- 5. Building component/system in good condition, requires no repair.

And the MEP and Hazardous Materials reports utilized the following grading system:

Good: Building component/system in good condition and requires little to no work

Fair: Building component/system in working condition but does require maintenance or some

upgrade

Poor: Building component/system is in need of replacement.

Respectfully,

Jonathan Claeys, AIA

#### **2018 MAIN STREET**

#### Parcel Info

One structure Lot Size: 12,500 SF

Existing Structure: Vacant Retail/Residential

Year Built: 1928

Structure GFA: 33,699 SF Structural Height: Three Story

Zoning: C2-A

Mixed-Use Commercial

#### **STRUCTURAL**

No access due to fire damage.

### **ARCHITECTURAL**

No access due to fire damage, building is a 3-story brick structure. Google Earth imagery shows extensive fire damage to the third floor and roof on the west end of the structure. It is assumed that fire and water damage have compromised the structural integrity of the building and that a complete demolition is necessary.

#### **MEPFP**

No access due to fire damage.

#### **HAZARDOUS MATERIALS**

No access due to fire damage

SEE ATTACHED APPENDICES FOR INDIVIDUAL FIELD REPORTS BY TRADE



### **BUILDING SURVEY**



PROPERTY EVALUATED: 2018 Main St

Niagara Falls, NY 14305

SURVEY DATE: 10.17.2018

CATEGROY	DESCRIPTION	CONDITION (1-5)	ADDITIONAL NOTES
	SITE ANA	ALYSIS	
Neighborhood Type	Commercial		
Access From Street	Pedestrian access		
Parking	Street parking		
Walks	On (1) sides of building (East)		
	CONSTRUCTION TYPE,	SYSTEMS, FINISHES	
Construction Type	Unknown	?	
Foundations	Unknown	?	
Frame	Unknown	?	
Roof	Unknown	?	
Exterior Walls	Brick	?	
Windows & Doors	Original wood	?	
Interiors			
Walls	Unknown	?	
Ceilings	Unknown	?	
Floors	Unknown	?	
	ACCESSI	BILITY	
Elevator(s)	Uknown		<u> </u>
Plumbing	Unknown		
Building Access	Yes - from Main St.		

See attached photos


### **BUILDING SURVEY PHOTOS**



PROPERTY EVALUATED: 2018 Main St

Niagara Falls, NY 14305

SURVEY DATE: 10.17.2018





# MEP Building Survey



Build	ing Name:	2018 Main St.			Da	ite: 10/1	7/18	
Occu	pancy Type:							
Squa	re Feet: 33,	699	Stories Tall:	3		Year Buil	t: <u>1928</u>	
<u>Gene</u>	ral Overall Co	ondition:						
No acc	cess due to fire	damage.						
HVAC	Observation	<u>15</u>						
1	Hooting Syst	tom						
1.	rieating Syst	tem:			Condition:	Poor	Fair	Good
2.	A/C System:							
					Condition:	Poor	_ Fair _	Good
3.	Ventilation S	system:						
					Condition:	Poor	_ Fair	Good
4.		Controls:				Door	Foir	Cood
		01			Condition:	P00i	_ rall	Good
<u> Pium</u>	bing/Fire Pro	tection Observa	ations					
5.		-						Y N
			BFP: Y_	_ N	<del></del>	·		Good
6.	Fire Water Se		DED: V	NI.				Y N
7.	Natural Gas S	Service:	BFP. T_	N _	Condition.	P00I	raii	Good
		-			Condition:	Poor	Fair	Good
8.	Domestic Hot	Motor Cyatomy						
					_ Condition:	Poor	Fair	Good
9.	Sanitary Sewe	er System:						
40	Ot \\/	0 /D f D i	O t		_ Condition:	Poor	Fair	Good
10.	Storm water	Sewer/Roof Draina	age System:		Condition:	Poor	Fair	Good
11.	Plumbing Fixt	ures:					' ' ' ' '	
	-							
					Condition:	Poor	Fair	Good
12.	Sprinkler/Star	ndpipe System:			_ Condition:	Poor	Fair	Good

# MEP Building Survey



## **Electrical Observations**

13.	Electrical Service Over	head	Underground	Mete	r Location	Inside	_ Outside
	Voltage: 208 240 _	480	Other Am	pacity: 100	225	400 _	Other
				_ Condition:	Poor	Fair	Good
14.	Electrical Distribution:	Fuses	Breakers				
				_ Condition:	Poor	Fair	Good
15.	Backup Power: Gas						
						Fair	Good
16.	Lighting:						
						Fair	Good
17.	Emergency Lighting:						
40					Poor	Fair	Good
18.	Tel/Data:				Door	Foir	Cood
10						raii	Good
13.	Fire Alarm System:					Fair	Good
20	CO Detection:					' ' ' ' ' '	0000
_0.						Fair	Good
21.	Other Systems:					_	
						Fair	Good
'44!t	ional Comments/ Code			_		_	
laan	ional comments, code	133063					