

Property Report:

Property Contact Information:
Contact Name:
Contact Phone Number:
Contact Email Address:
Property Information:
Property Address: 231 7074 5T
Property SBL#:
Approximate Year Built:
Approximate Square Footage: 12.00
Number of Bedroom_3
Number of Bath 1 2
Property Development Summary: Please describe below the preferred redevelopment plan and include any noteworthy results the municipality would like NORLIC to take into consideration, i.e. owner occupancy, desired tenant, etc. (Please use additional pages if necessary)

1. Grounds

Grading:
Grading Slope Flat, Minor, Moderate, Steep, Very Steep
Grading Conditions Comments:
Driveway/Sidewalk & Walkways:
Driveway/Sidewalk material Gravel Concrete, Asphalt
Driveway/Sidewalk Conditions Comments: OLO G-RAVEL DRIVEWAY OUTR GROWKIN FRONT SIDEWAYLE - FAIR
Vegetation:
Vegetation Conditions Comments: ALC UEC-ETATION IS OUER C-ROWXI
Retaining Wall:
Retaining Wall Material: Concrete, Wood
Retaining Wall Conditions N P Comments:
Other Conditions Comments:
Note: Inspect electrical service conditions while outside.
2. Exterior
Entrance Conditions:
Front Entrance Type: Covered/Uncovered, Patio, Forch, Deck
Front Entrance Conditions POOR Comments: FRONT STEPS NEED TO DE UREPLACED
PORCH ROOF LOOKS SOUND, PORCH FLOOR, WALL,
AND POSTS ARE BAD, NEEDS FOUNDATION WORK

Rear Entrance Conditions BAD Comments: REAR DECK -UNFINISLED NEEDS TO BE DEMOLISHED Exterior Walls/Trim: Structure Type: Wood Frame, Brick/Masonry, Log Exterior Wall Covering: Wood, Vinyl, Metal, Brick, Stone, Stucco, Veneer, EIFS Exterior Wall Conditions Comments: SIDING OVERALL IN GOOD CONDITION Trim material: Wood, Vinyl, Brick Trim Conditions FAIR Comments: SomE AREAS NEED ATTENTION Eave/Soffit/Fascia: Conditions FAIR Comments: OUTA ALL GOOD -NETO SUME REPAIRS Windows/Exterior Doors: Window Material: Aluminum, Wood, Vinyl Window Type: Sliding, Casement, Double Hung, Single Hung, Louver Window Conditions FAIR COMMENTS: FAIR CONDITION - ZND FLOOR BATH-REPLACE OR REMOVE - ITS IN THE SHOWER Door Conditions Comments HLL BASEMENT WINDOWS MISSING OR BROKEN **Exterior Water Spickets:** Faucet Conditions Comments: No Spicots Found

Rear Entrance Type: Covered/Uncovered, Patio, Porch, Deck

3. Roofing

Roof Covering: Method of Inspection: Walked on, Viewed from ladder, Not fully visible Roof Style: Hip, Gable, Mansard Shed, Gambrel Roof Covering Material: Composition shingle, Metal, Clay, Wood Shingles/Shakes Number of Layers: One, Two, Three, Four or more, Undetermined Roof Condition Pool Comments: NFEDS NEW ROOF Flashing Conditions MA Comments: Condition of Roof Penetrations Comments: NOT SEEN Gutter and Downspout Conditions Comments: No GUTTERS, NO DOWN SPOUTS. Chimney: Chimney Material: Brick, Block, Concrete, Stone Chimney Conditions Comment: Attic: Access Location NONE Method of Inspection: Entered Attic, No Access, Viewed from Access Entrance Only Roof Frame Type: Rafters, Trusses Roof Frame Condition N/B Comments: Ceiling Frame Type Joists Trusses

Ceiling Frame Condition Comments:
Attic Ventilation Type: Gabel End, Ridge, Soffit, Rotary Vent Attic Ventilation Conditions Comments:
Insulation Type: Blown in, Rolled Fiberglass, Combination, None Present Insulation Conditions Comments:
Attic Fan Condition N/A- Comments: No ACCESS
4. Heating/Air
Heating:
Location of Unit_BASEWENT
Heating Type: Forced Air, Gravity, Radiant, Boiler, Floor/Wall, Heat Pump
Energy Source: Natural Gas, Oil, Wood/Coal, Electric
Heating Unit Condition Comments: FURNACE WAS REMOVED
Distribution Type: Registers, Gravity, Radiators, Convectors, Baseboard
Distribution Conditions Comments:
Ventilation Conditions Comment:
Thermostat Condition Comments:

Air Conditioning/Cooling:
Cooling System Type: Split System, Evaporative Cooler, Window/Wall Unit, Heat Pump
A/C Unit Power: 120V, 240V
Unit Conditions A Comments:
A/C Line Conditions A/A Comments:
Fireplace:
Fireplace Location 4/14
Fireplace Type: Wood Burning, Natural Gas, Propane, Ventless Gas
Fireplace Conditions Comments:
5. Electrical Service Drop/Weatherhead:
Electrical Servine Type/Material: Overhead/Underground, Copper/Aluminum
Number of Conductors: Two, Three, Four
Electrical Service Condition Comments: FUGE BOX - ELECTRIC
Grounding Condition Comments
Main Electrical Panel:
Main Disconnect Location: At Main Panel, Outside at Meter, Other 13567
Main Panel Location 35 ty
Panel Amperage Rating: 60, 100, 150, 200, Other

Circuit Protection Type: Breakers, Fuses
Main Panel Conditions Comments: NEGOS OFGRADE
Wiring:
Conductor Type: Copper, Aluminum
Wiring Method: Plastic-Sheathed, Cloth-Sheathed, Knob & Tube
Conditions Comments:
Electrical subpanel(s):
Subpanel ocation(s) N/14
Subpanel Conditions Comments:
6. Plumbing
Water Main Line:
Main shutoff Location BSMT
Main Line Material: Copper Galvanized Steel, Plastic/PVC, Lead
Main Line & Valve Condition Cos Comments:
Water Supply Lines:
Supply Line Material: Copper, Galvanized, Plastic/PVC, Lead
Supply Line Conditions <u>Poor</u> Comments: <u>ALL COPPER IN LOUSE</u> 1485 355N REMOVED
Drain/Waste Lines:
Drain Line Material: Plastic/PVC, Galvanized, Lead, Copper

Drain Line Conditions Comments:
Plumbing Vent System:
Plumbing Vent Pipe Material: Plastic/PVC, Copper, Galvanized CAST 1ROH
Plumbing Vent Conditions Comments:
Gas/Oil Fuel Systems:
Main Shutoff Location 35 th T
Fuel Line Material: Black Steel, Copper
Fuel Line Conditions FALR Comments
Fuel Storage Tank Condition Comments: OLD OIL TANK
Water Heater(s):
Water Heater Type: Gas, Electric
Water Heater Location No WATER HEATER
Capacity: Gallons
Water Heater Conditions Comments
7. Interiors:
Interior Walls/Ceilings/Floors:
Wall Conditions Prop Comments: ALL WALLS & CELLINGS

Ceiling Conditions Pook Comments: HOLES OR UNEIHISHED
Floor Conditions N/H Comments:
Closet Conditions FAIR Comments: NO DOOR S
Heating Source Conditions M/P Comments:
Windows/Doors:
Interior Window Conditions Comments: BEDROOM DOURS DAMAGED OR WISSING NO BATH DOORS ZNO EL
Interior Door Conditions Comments:
Interiors Electrical Conditions: Electrical Conditions Comments: ELECTRIC NEEDS UPCRADE Lighting Conditions Comments: NO ELECTRIC
Lighting Conditions Confinents
Ceiling Fan Conditions Managements:
Smoke Detectors Present? Yes No Comments:
8. Kitchen
Walls/Ceilings/Floors:
Wall Conditions Park Comments: ALL NEED REPAIRS

Ceiling Conditions Comments:
Floor Conditions Comments:
Closet Conditions Comments:
Heating Source Conditions Comments:
Windows/Doors:
Kitchen Window Conditions Comments:
Kitchen Door Conditions Comments: 13 OUR 15 BLOCKED OFF
Kitchen Electrical Conditions: Electrical Conditions Comments: ELECTRIC NEEDS UPG-RHOF TO COOE Lighting Conditions Comments:
Ceiling Fan Conditions tyle Comments:
Sink/Counter Tops/Cabinets:
Counter Condition Comments: DAMAGEO WLEW SINK WAS REMOVED Cabinet Conditions Comments: NEWER CHAINETS - SOME DAMAGE Sink Plumbing Conditions Comments: NO SINK
Sink Faucet Condition Comments: No FauceT Garbage Disposal Condition A Comments:

Appliances:
Stove/Range Type: Electric, Gas, Combo
Stove/Range Conditions Comments:
Hood/Fan Condition // Comments:
Dishwasher Condition A Comments:
Refrigerator Condition Comments:
9. Bath(s):
Walls/Ceilings/Floors:
Wall Conditions Pow & Comments: NEED REPAIR
Ceiling Conditions Comments: NEGO REPAIR
Floor Conditions Comments: NEEDS FLOOR
Closet Conditions NA Comments: No DuoRS
Heating Source Conditions N/H Comments: HLL HOUSE HEAT HAS BEEN REMOVED
Windows/Doors:
Window Conditions POOR Comments: WINDOW IN TUB PREA
Door Conditions Comments: No 1200 RS

Bathroom Electrical Conditions: Electrical Conditions____ Comments: NEEDS UPGRADE Lighting Conditions Comments: NEEDS UPGRADE Ventilation Fan Conditions N/H Comments: Sink/Plumbing: Counter/Cabinet Conditions FRIR Comments: Sink Drain Conditions N V Comments: Faucet Conditions N/H Comments: Shower/Tub/Toilet: Shower Enclosure Condition N/A Comments: Tub Condition POOR Comments: NO PLUMBING Bath Faucet Condition Comments: No 12LUMBING

Toilet Condition Comments: UNKNOWN

10. Basement:

Basement Walls/Ceilings/Floors:

Wall Conditions Good Comments: BLOCK WALLS - NO VISABLE CRAKS
Ceiling Conditions Comments:
Floor Conditions Comments: NO VISHBLE SIGNS OF CRACKS - NO MUSTY SMECL Closet Conditions Comments:
Closer Conditional y
Heating Source Conditions Comments:
Windows/Doors: Window Conditions Comments: BASEMENT WINDOWS MISSING UR BROKEN Door Conditions NA Comments:
Electrical Conditions: Electrical Conditions Comments:
Sump Pump Conditions Comments: No Sump Found
Other Basement Conditions Comments:

11. Garage/Laundry:

Garage:
Garage Type: Attached/Detached, Finished/Unfinished
Exterior Siding Condition (if detached)Comments:
Roofing Condition (if detached) Comments:
Garage Interiors:
Wall Conditions Comments:
Ceiling Conditions Comments:
Floor Conditions Comments:
Window Conditions Comments:
WINDOW CONDITIONS
Door Conditions Comments:
Electrical/Lighting Conditions Comments:
Garage Vehicle Door:
Vehicle Door Condition Comments:
Automatic Door Opener Condition: Comments:
Laundry Room:
Laundry Room Conditions . Comments:

12. Foundation/Crawl Space:

Foundation: 566 BS mT
Access Method: Entered Crawl Space, Viewed from Access, No Access
Access Condition Comments:
Foundation Type: Crawl Space, Basement, Slab on Grade
Foundation Material: Poured Concrete, Concrete Block, Brick, Stone, Wood
Foundation Conditions Comments:
Column Type: Poured Concrete, Concrete Block, Brick, Stone, Wood, Steel Column Conditions Comments:
Ventilation Conditions Comments:
Flooring/Structure:
Flooring Support Type: Joists, Trusses
Flooring Support Conditions Comments:
Crawl Space Insulation/Vapor Barrier: Insulation Conditions Comments: Vapor Barrier Conditions Comments:
Other Crawl Space Conditions: